Altimeter/

FAR91.41 part 43 ag ATC Trai AltEncod Std Altin Details WO#

with cu

return t

RECORDING YEAR: TACH TIME

DATE

TODAYS FLIGHT

TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterati

Entries must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entri-



3490 S. Fortuna Ave. Yuma, AZ. 85634

N6298E Cessna 182 Serial No. 18268358 Total Time: 12797.9 Date: 11/19/2011

Accomplished the following inspections, maintenance and due items:

Complied with Annual inspection as per the current Cessna 182 maintenance manual.

Defueled aircraft to verify fuel gage accuracy- with no defects noted.

Installed new ELT 406MHz transmitter as per USCS/Border protection SOW 10-165 using kit P/N 455-5041. Weight & balance is negligible aircraft equipment list updated to reflect these changes. See FAA form 337 attached to this W/O 6298E-2012-M-0001-0001

AD 11-10-09 seat rail inspections complied with both pilot & co-pilot inbd. seat tracks replaced P/N 0710658-2.

Removed and replaced engine air filter with new unit Bracket P/N BA-8103-1

Changed engine oil and filter, Used a CH-48109-1 oil filter and 10qts. S-Shell 50wt. oil.

Installed secondary seat stops Pilot & Copilot as per Cessna SEB07-05

Removed and replaced fire extinguisher bracket with new unit P/N C421001-0202

ELT removed and sent to Mfgr. This date and time for reprogramming. Instrument panel has placard installed at ELT switch stating ELT

Details of work performed are on file at this work center under Work Order number: 6298E-2012-I-0009-0001. All necessary leak checks and operational checks were performed and no defects were noted. This aircraft is approved for return to service. I certify this aircraft is airworthy with respect to the work preformed and is approved for return to service.

Andrew M. Bush-Quality Control Inspector

AP 3456641 IA

